



# VICTORIAN HANG GLIDING AND PARAGLIDING ASSOCIATION

Site Assessment Report (ref. Parks Vic License, Schedule 1, para 3.2)

SITE					
Site Name	CAPE BRIDGWATER		Date of inspection	11 / 6 / 2017	
Site Inspected by	Ryanch Kloa	HGFA no. / Position	33153	Signature	Ryanch Kloa
Report Reviewed by	Peter Mannah	HGFA no. / Position	34760	Signature	Peter Mannah

## RESULTS OF ASSESSMENT

Assessed as satisfactory at date of Inspection?	Comments
- <input checked="" type="radio"/> Yes / <input type="radio"/> No	-

## NOTES/ACTIONS

Items	Comments
-	-

## CHECKLIST AID

CHECKLIST ITEMS	STATUS (tick appropriate box)			Describe action required (if any)
	Not Applicable	Good	Needs attention	
Site Guide contents for site		✓		
Access track condition	✗			
Emergency Marker Post	✗			
Site signage	✗			
Fencing/Barriers	✗			
Set up area		✓		
Launch area		✓		
Launch structure	✗			
Vegetation		✓		
Clear of rubbish		✓		
Other				

## PLANS FOR MANAGEMENT OF SITE

--