



VICTORIAN HANG GLIDING AND PARAGLIDING ASSOCIATION

Site Assessment Report (ref. Parks Vic License, Schedule 1, para 3.2)

SITE				
Site Name	MT DANDENONG		Date of inspection	15/12/17
Site Inspected by	M. PIKE	HGFA no. / Position	33713	Signature
Report Reviewed by		HGFA no. / Position	37135 / Site Dev. Officer	Signature
				S. H. Norman

RESULTS OF ASSESSMENT	
Assessed as satisfactory at date of inspection?	Comments
- <input checked="" type="radio"/> Yes / <input type="radio"/> No	- SEASONAL LONG GRASS - RAMP STRUCTURAL SOUND

NOTES/ACTIONS	
Items	Comments
- RUBBISH	- MINOR RUBBISH ITEMS REMOVED - SITE CLEAN

CHECKLIST AID				
CHECKLIST ITEMS	STATUS (tick appropriate box)			Describe action required (if any)
	Not Applicable	Good	Needs attention	
Site Guide contents for site		✓		
Access track condition	✓			
Emergency Marker Post			✓	REMOVE GRAFFITI / NOT PRESENT
Site signage				NOT PRESENT - REF PV.
Fencing/Barriers	✓			
Set up area		✓		
Launch area		✓		
Launch structure		✓		SOLID FOOTINGS / SURFACE GOOD
Vegetation		✓		
Clear of rubbish		✓		
Other				

PLANS FOR MANAGEMENT OF SITE
PAIN OVER GRAFFITI