



VICTORIAN HANG GLIDING AND PARAGLIDING ASSOCIATION

Site Assessment Report (ref. Parks Vic License, Schedule 1, para 3.2)

SITE					
Site Name	SOUTH SIDE		Date of inspection	15/12/2017	
Site Inspected by	ROB VAN DER KLOOSTER	HGFA no. / Position	33153	Signature	<i>Rob van der Klooster</i>
Report Reviewed by	PETER HANNAH	HGFA no. / Position	34760	Signature	<i>Peter Hannah</i>

RESULTS OF ASSESSMENT

Assessed as satisfactory at date of inspection?	Comments
- Yes/No	-

NOTES/ACTIONS

Items	Comments
-	-

CHECKLIST AID

CHECKLIST ITEMS	STATUS (tick appropriate box)			Describe action required (if any)
	Not Applicable	Good	Needs attention	
Site Guide contents for site		✓		
Access track condition		✓		
Emergency Marker Post	✗			
Site signage		✓		INSTALLED EXTRA CLIFF WARNING SIGN
Fencing/Barriers		✓		
Set up area		✓		
Launch area		✓		
Launch structure		✓		
Vegetation		✓		
Clear of rubbish		✓		
Other				

PLANS FOR MANAGEMENT OF SITE

--